


XTH–01000F–K
Units: inches [mm]
Scale: Full
TEMPERATURE TRANSMITTER T/C TYPE K INPUT, HEAD MOUNT 0 - 1000 DEG. F
AUTOMATIONDIRECT.com