


XTH–N100100F–T
Units: inches [mm]
Scale: Full
TEMPERATURE TRANSMITTER T/C TYPE T INPUT, HEAD MOUNT -100 TO 100 DEG. F
AUTOMATIONDIRECT.com