



NOTES:

1. DIMENSIONS CAN BE CHANGED BY MANUFACTURER WITHOUT NOTICE.
2. DIMENSIONS DO NOT IMPLY TOLERANCE.

P1-01AC
Units: mm [inches] Scale: Full
PRODUCTIVITY 1000 POWER SUPPLY
 AUTOMATIONDIRECT [®] CO.