



NOTES:

1. DIMENSIONS CAN BE CHANGED BY MANUFACTURER WITHOUT NOTICE.
2. DIMENSIONS DO NOT IMPLY TOLERANCE.

P1-RX
Units: mm [inches]
Scale: Full
PRODUCTIVITY 1000 REMOTE SLAVE
AUTOMATIONDIRECT [®] CO.