



Notes:

1. Dimensions can be changed by Manufacturer without notice.
2. Dimensions do not imply tolerance.

P2-16TR
Units: mm [inches]
Scale: Full
PRODUCTIVITY 2000
16 POINT RELAY OUTPUT
(16 FORM A)
AUTOMATIONDIRECT .com