


Notes:

1. Dimensions can be changed by Manufacturer without notice.
2. Dimensions do not imply tolerance.

P2-HSI
Units: mm [inches]
Scale: Full
PRODUCTIVITY 2000 2 CH HIGH SPEED COUNTER INPUT
 AUTOMATIONDIRECT .com