



NOTES:

1. DIMENSIONS CAN BE CHANGED BY MANUFACTURER WITHOUT NOTICE.
2. DIMENSIONS DO NOT IMPLY TOLERANCE.

P1-4ADL2DAL-2

Units: mm [inches]

Scale: Full

**PRODUCTIVITY 1000 ANALOG,
4 POINT 0-5VDC IN/OUT,
2 POINT 0-10VDC IN/OUT**

AUTOMATIONDIRECT
1000