



Notes:

1. Dimensions can be changed by Manufacturer without notice.
2. Dimensions do not imply tolerance.

P2-08TRS
Units: mm [inches]
Scale: Full
PRODUCTIVITY 2000
8 PT ISOLATED RELAY OUTPUT
(8 FORM A)
 AUTOMATIONDIRECT [®] co.