



Notes:

1. Dimensions can be changed by Manufacturer without notice.
2. Dimensions do not imply tolerance.

P2-RTB
Units: mm [inches] Scale: Full
PRODUCTIVITY 2000 SCREW TERMINAL BLOCK
 AUTOMATIONDIRECT .com