



Notes:

1. Dimensions can be changed by Manufacturer without notice.
2. Dimensions do not imply tolerance.

PX-314
Units: mm [inches]
Scale: Full
4CH ANALOG INPUT, VOLTAGE, 12-BIT, FOR PROTOS X I/O
 AUTOMATIONDIRECT .com