



Notes:

1. Dimensions can be changed by Manufacturer without notice.
2. Dimensions do not imply tolerance.

PX-414

Units: mm [inches]

Scale: Full

4CH ANALOG OUTPUT,
VOLTAGE ,12-BIT,
FOR PROTOS X I/O

AUTOMATIONDIRECT.com