



XTH-01000F-J
Units: inches [mm]
Scale: Full
TEMPERATURE TRANSMITTER
T/C TYPE J INPUT, HEAD MOUNT
0 - 1000 DEG. F
 AUTOMATIONDIRECT .com