


XTH-0100F-K
Units: inches [mm]
Scale: Full
TEMPERATURE TRANSMITTER
T/C TYPE K INPUT, HEAD MOUNT
0 - 100 DEG. F
 AUTOMATIONDIRECT .com