



XTH-0500F-PT1

Units: inches [mm]

Scale: Full

TEMPERATURE TRANSMITTER  
RTD Pt100 INPUT, HEAD MOUNT  
0 - 500 DEG. F

 **AUTOMATIONDIRECT**.com