






General tolerances if not otherwise specified

NDM DIM mm		Tool Class		
From	To	A	B	C
<1>	6	± 0.05	± 0.1	± 0.2
<6>	30	± 0.1	± 0.2	± 0.5
<30>	100	± 0.15	± 0.3	± 0.8
<100>	300	± 0.2	± 0.5	± 1.2
<300>	1000	± 0.3	± 0.8	± 2
Holes H 13				



DN-CST
Units: [Inches] mm
Scale: Full
Cable stripping tool